

Contents

| | |
|---|-----------|
| Introduction | 7 |
| 1 Exercise L1: PC sequential control | 9 |
| 1.1 Introduction | 9 |
| 1.1.1 State machines | 11 |
| 1.1.2 Moore machine | 12 |
| 1.1.3 Mealy machine | 12 |
| 1.2 Example: Cipher lock | 13 |
| 1.2.1 Moore machine for a cipher lock | 14 |
| 1.2.2 Edge detection | 15 |
| 1.2.3 Time delays | 16 |
| 1.2.4 Timer TON | 16 |
| 1.2.5 Mealy machine for the cipher lock after corrections | 17 |
| 1.3 Visual Studio 2019 | 19 |
| 1.3.1 Main view | 19 |
| 1.3.2 Running and debugging a program | 19 |
| 1.4 Program implementation | 21 |
| 1.4.1 Moore machine in C++ | 21 |
| 1.4.2 Mealy machine in C++ | 26 |
| 1.4.3 Communication with processes | 26 |
| 1.4.4 Connection with processes | 28 |
| 1.5 Implementation of the exercise | 30 |
| 2 Exercise L2: PLC sequential control | 31 |
| 2.1 Introduction | 31 |
| 2.2 PLC programming languages | 32 |
| 2.3 Example ST Language program: cipher lock | 35 |
| 2.4 Description of GX Works3 software | 39 |
| 2.4.1 Creating a new project | 39 |
| 2.4.2 Types of available programs | 41 |
| 2.4.3 Variables and labels | 43 |
| 2.4.4 Code compilation | 45 |
| 2.4.5 Diagnostics, monitoring of program operation | 46 |
| 2.5 Implementation of the exercise | 48 |
| 3 Exercise L3: HMI and SCADA systems | 49 |
| 3.1 Introduction | 49 |
| 3.2 Description of the control system | 51 |
| 3.3 Implementation of SCADA MAPS visualization | 52 |

| | | |
|----------|---|------------|
| 3.3.1 | Starting SCADA MAPS | 52 |
| 3.3.2 | Agents | 53 |
| 3.3.3 | Behaviors | 60 |
| 3.3.4 | Configuration of spiders | 63 |
| 3.4 | Implementation of the exercise | 68 |
| 4 | Exercise L4: PID control | 70 |
| 4.1 | Introduction | 70 |
| 4.2 | PID controller tuning with SCADA MAPS | 81 |
| 4.3 | Implementation of the exercise | 84 |
| 5 | Exercise L5: Servomechanism | 86 |
| 5.1 | Introduction | 86 |
| 5.1.1 | Structure of the servomechanism | 88 |
| 5.1.2 | The structure of the frequency inverter | 93 |
| 5.1.3 | Safety in working with a laboratory stand | 97 |
| 5.2 | Control of the frequency inverter | 99 |
| 5.2.1 | Task: Setting the inverter parameters | 99 |
| 5.2.2 | Task: Open loop scalar control – Speed setting with analog signal | 99 |
| 5.2.3 | Task: Closed loop scalar control – position setting | 103 |
| 5.2.4 | Task: Scalar control – execution of homing | 106 |
| 5.3 | MR Configurator2: Basic servo configuration | 107 |
| 5.3.1 | Basic amplifier parameters | 110 |
| 5.3.2 | Basic amplifier diagnostics | 112 |
| 5.4 | MR Configurator2: Basic tuning of the servo motor | 112 |
| 5.4.1 | Basic tuning of the servo motor: parameter preparation | 112 |
| 5.4.2 | Task: Tuning the dynamic response of the servo system | 118 |
| 5.5 | Motion Control: Analog and Digital Interface | 130 |
| 5.5.1 | Task: Control in speed mode | 131 |
| 5.5.2 | Task: Position control mode | 139 |
| 5.6 | Motion Control: Ethernet interface | 148 |
| 5.6.1 | Task: Ethernet interface – amplifier parameterisation | 148 |
| 5.6.2 | Task: Ethernet interface – PLC configuration | 149 |
| 5.6.3 | Task: Ethernet interface – communication with servo | 154 |
| 5.6.4 | Task: Ethernet interface – servo homing | 156 |
| 5.6.5 | Task: Ethernet interface – speed control | 156 |
| 5.6.6 | Task: Ethernet interface – position control | 158 |
| 5.7 | Task: Synchronised knife application | 158 |
| 5.8 | Implementation of the exercise | 161 |
| 6 | Laboratory workstations and processes | 162 |
| 6.1 | Workstation without a motor | 162 |
| 6.2 | Workstation with a motor | 164 |
| 6.3 | Sorting line | 166 |
| 6.4 | Assembly line | 168 |
| 6.5 | Production line | 170 |
| 6.6 | Gripper arm | 172 |
| 6.7 | Punching machine | 174 |